


North and west sides of remediation building, showing replaced bottom trim and other replaced sections, including door jam.



View of east side of remediation building after being re-painted.



View of west side of remediation building after being re-painted.



View of north side of remediation building after being re-painted.