

PRS REMEDIATION SITE VISIT FORM

PETROLEUM REMEDIATION SECTION

Facility: <u>Boice Crane</u>	Type: <u>SPARC</u> RP
Address: <u>120 W 8th Street</u>	City: <u>Bothenburg</u>
NDEE ID: <u>8568</u>	Program: <u>LST</u> / RA # <u>090892-NM-1600</u>
Consultant: <u>PG & E</u>	
Latitude: <u>40°55'45.02" N</u>	Longitude: <u>100°10'01.77 W</u>
Visited by: <u>Quinn Krikal</u>	Site Visit Date: <u>June 1, 2022</u>

Monitor Wells	
All monitor wells searched for were found to be in satisfactory condition except as noted below:	
Well #	Condition / Comments:
/	/

Recovery System
Recovery System type: None ___ SVE <input checked="" type="checkbox"/> AS <input checked="" type="checkbox"/> Dual Phase ___ Other: _____
Recovery Structure: Trailer (plate #) <u>no plate</u> Building ___ Other: _____
Recovery Structure condition: Good <input checked="" type="checkbox"/> Other: _____
Recovery System is running: Yes <input checked="" type="checkbox"/> Other: _____
Recovery System comments / observations: <u>The remediation system was operating at the time of my visit</u> <u>VIN 5JWTC1624MN562022</u>

Other Comments / Notes / Observations
/

PRS PM Initials: <u>N</u>	Date: <u>6/2/2022</u>
---------------------------	-----------------------